



IDAHO DEPARTMENT OF  
HEALTH & WELFARE

C.L. "BUTCH" OTTER, Governor  
RICHARD M. ARMSTRONG – Director

DEBBY RANSOM, R.N., R.H.I.T. – Chief  
BUREAU OF FACILITY STANDARDS  
3232 Elder Street  
P.O. Box 83720  
Boise, Idaho 83720-0036  
PHONE: (208) 334-6626  
FAX: (208) 364-1888  
E-mail: [fsb@idhw.state.id.us](mailto:fsb@idhw.state.id.us)

January 11, 2007

Linda Palmer, Administrator  
Beehive Homes of Treasure Valley - Assisted Living  
3211 Kellen Circle  
Nampa, ID 83686

Dear Ms. Palmer:

On January 3, 2007, a life safety code survey was conducted at Beehive Homes of Treasure Valley - Assisted Living Centers, Inc. The facility was found to be providing a safe environment for its residents.

The enclosed form, stating no core issue deficiencies were cited during the survey, is for your records only and need not be returned.

Should you have any questions about our visit, please contact me at (208) 334-6626.

Sincerely,

A handwritten signature in black ink, appearing to read 'M. Grimes', with a long horizontal flourish extending to the right.

MARK GRIMES  
Supervisor  
Facility Fire Safety & Construction Program

MG/slc

Enclosure

Bureau of Facility Standards

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  <b>13R747</b>	(X2) MULTIPLE CONSTRUCTION A. BUILDING <b>01 - ENTIRE BUILDING</b> B. WING _____	(X3) DATE SURVEY COMPLETED  <b>01/03/2007</b>
NAME OF PROVIDER OR SUPPLIER  <b>BEEHIVE HOMES OF TREASURE VALLEY - AS</b>		STREET ADDRESS, CITY, STATE, ZIP CODE <b>612 E MARYLAND ST NAMPA, ID 83686</b>		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
R 000	<p>Initial Comments</p> <p>The facility was found to be in substantial compliance with the fire and life safety requirements of the Rules for Residential or Assisted Living Facilities in Idaho. No core deficiencies were cited during the standard fire/life safety survey conducted on January 3, 2007.</p> <p>The surveyor conducting the survey was:</p> <p>Chris Laumann Health Facility Surveyor Facility Fire safety &amp; Construction</p>	R 000		

Bureau of Facility Standards

TITLE

(X6) DATE

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

STATE FORM

6899

R0IG21

If continuation sheet 1 of 1